




P0001 (AEG EBHH/SH 2CO)




2TAZ941070R0001

Auxiliary contact-Signal contact/Auxiliary contact
Hilfsschalter-Signalkontakt/Hilfsschalter
Contatto ausiliario/ausiliario - Contatto di scattato/
ausiliario

AEG



Made in P.R.C



2TAB947002P0001



Warning! Installation by person with electrotechnical expertise only.
Warnung! Installation nur durch elektrotechnische Fachkraft.
Avvertenza! Fare installare solo da un elettricista qualificato.
Avertissement! Installation uniquement par des personnes qualifiées en électrotechnique.
¡Advertencia! La instalación deberá ser realizada únicamente por electricistas especializados.

P0002 (AEG EAH/S 1CO)


2TAZ941080R0002

Auxiliary/Signal contact
Signalkontakt/Hilfsschalter
Contatto ausiliario/Contatto di scatto


AEG





Remove/Rimuovere RCCB pin	Remove/Rimuovere MCB pin
EN40	FN
EN60	EXI
EN100	
EN250	
EX45 EX60	
EX100	
EX100 UC	
DN45	
DN60	
DN100	
ESD	
DX60	
DX100	
EAF	



Made in P.R.C



Warning! Installation by person with electrotechnical expertise only.
Warnung! Installation nur durch elektrotechnische Fachkraft.
Avvertenza! Fare installare solo da un elettricista qualificato.
Avertissement! Installation uniquement par des personnes qualifiées en électrotechnique.
¡Advertencia! La instalación deberá ser realizada únicamente por electricistas especializados.



2TAB947002P0002